-Date: Uşer:

Friday, 7/4/2008 8:45:33 AM

Kim Johnston

Process Sheet

Customer

: CU-DAR001 Dart Helicopters Services

Type

Drawing Name

: BLADE POSITIONER WELDMENT

Job Number

: 40241

Estimate Number

: 13443

P.O. Number

: 7/4/2008

Part Number

: PB674300129

This Issue

S.O. No. : **Drawing Number** · B6743001 P.40

Prsht Rev.

: NC

Project Number

First Issue

Drawing Revision

: N/A

: //

: B1

Previous Run

Written By

Material Due Date

: 7/10/2008

Qty:

5 Um:

Each

Checked & Approved By

Comment

08-06-27

: LARGE FAB ASSY

new issue DD verified by:ec

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

1.0

PB6743001313

Plate



Comment: Qtv.:

1.0000 Each(s)/Unit

Total:

5.0000 Each(s)

Plate

batch: 2 PB6743001319

Gusset



Comment: Qty.:

2.0000 Each(s)/Unit

Total:

10.0000 Each(s)

Gusset

batch;

Upper Pad Assembly

PB674300133

Upper Pad Assembly



3.0

2.0

10.0000 Each(s)



Comment: Qty.:

2.0000 Each(s)/Unit

Total:

batch: 10 40 6

LARGE FABRICATION RESOURCE 1



4.0

LARGE FAB

Comment: LARGE FABRICATION RESOURCE 1

****FOR -337 LOCATE APPROX. AS SHOWN ASSURING 45 DEG. MOVEMENT OF -285 EACH SIDE OF

VERTICAL, PRIOR TO WELDING****

1- ASSEMBLE AND WELD AS PER DWG

5.0

QC9

VISUAL WELDING INSPECTION



Comment: VISUAL WELDING INSPECTION



Page 1

Form: rorocess


Dart Ae	rospace	Ltd							
W/O:			W	ORK ORDER CHANGES					
DATE STEP		PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			•						
1.	7.4			·			1		
Part No	•	PAR #:	Fault Cate	gory: N				Date: _ Date: _	
NCR:		•:	WORK ORD	ER NON-CONFORMANO	CE (NCF	R)			
DÁTE	0.750	Description of NC Corrective Action				Verifi	cation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date		ion C	Chief Eng	QC Inspector
							,		
							,	! -	
			1)		ı	1			1

NOTE: Date & initial all entries

Friday, 7/4/2008 8:45:33 AM Date: Kim Johnston User: **Process Sheet** Drawing Name: BLADE POSITIONER WELDMENT Customer: CU-DAR001 Dart Helicopters Services Part Number: PB674300129 Job Number: 40241 Job Number: Description: Seq. #: Machine Or Operation: INSPECT WORK TO CURRENT STEP 6.0 QC5 Comment: INSPECT WORK TO CURRENT STEP HAND FINISHING1 HAND FINISHING RESOURCE #1 Comment: HAND FINISHING RESOURCE #1 POWDER COATI POWDER COATING 8.0 M102316 Comment: POWDER COATING Powder Coat Green Sandtex (Ref: 4.3.5.8) as per QSI 005 4.3 START TIME: **OVEN TEMPERATURE:** FINISH TIME: INSPECT POWDER COAT/CHEMICAL CONVERSION 9.0 QC3 POWDER COAT/CHEMICAL CONVERSION PACKAGING RESOURCE #1 10.0 PACKAGING 1 Comment: PACKAGING RESOURCE #1 Identify and Stock Location: 11.0 QC21 Comment: FINAL INSPECTION/W/O RELEASE Job Completion

Dart Ae	rospace	Ltd										
W/O:			WC	ORK ORDER CH	ANGES							
DATE STEP		PR	PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
							· -		•			
Part No	•	PAR #:	Fault Cate	gory:	NC	R: Yes	No DQ	A:	_ Date: _			
						QA: N	C Close	d:	_ Date: _			
NCR:		,	WORK ORDI	ER NON-CONFO	RMANCE	(NCR)					
	0755	Description of NC	tion of NC Corrective Action		Section B		Verification		Approval	Approval		
DATE	STEP	Section A	Initial Chief Eng	Action Descrip Chief Eng	tion	Sign & Date	Section C		Section C		Chief Eng	QC Inspector
									······································			

NOTE: Date & initial all entries



Dart Aerospac	e Ltd
---------------	-------

W/O:			WORK ORDER	CHANGES				
DATE	STEP	PR	OCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Category:	NCR: Yes	No DQ	A:	Date:	

QA: N/C Closed: ____ Date: ___

NCR:	R: WORK ORDER NON-CONFORMANCE (NCR)							
		Description of NC		Corrective Action Section B				
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspector
					••			
								!
		unit fu						

NOTE: Date & initial all entries

DART	AEROSP	ACE LTD		Work Or	der:	399	152_	
					•	-7 ,-	1/2-	j *1/
Descrip	otion: 3	lade Tosit	eones Well	not Part Num	iber:	D67	1 -4300	1-di
		1/3	7		<u> </u>		B P	
Dwg:	<u> 367-</u>	-4300/	SHEET 40)	Qty:	-4	Page of	
						L	rage of	
Step	Location	Procedure				Ву	Date	Qty
1	DC	Issue Traveler						
		gusset 319 us	2 mat: 090 4	061-76 al. (M	7950			+ 7
cut	CAWA	gusser 319 us out 12.00" x 3. per day, drill deburt.	00" (mark po	it out on piece	2 asy	0		2
	J	per day, drill	Lole in Cen	iter as per a	uy.			
		alkun.						
		0/2 4 2 2 4 2 2	ing madi an	3 1-06/T/2 AL /	m 795	1		
a	GANY	place -3/3 (3/3	1. 24.5 X	25 (mark out	part	\$5		/
cur		plate -313 \$ 317 make as one pr and bend) de	but		7			
ļ	KI/A V	Olato - 222 11	w matings	wold Tle al (n	17950	}		10
cut	HACA	cut and mark	part for	berdien of Che	d	110		2
		Plate - 337 W but and mark as per chancing	5) dibur	<i>J</i>				
		all parts tog				1		1
weld	WH							
drill	GA	مان من مناه	sout is n	indo To	o te MA	el I	•	
and		wher isside and padding)	(but to) mat	ch hole on pa	H			
		1/4" Lole 7 Ke	les in total	<u>, , , , , , , , , , , , , , , , , , , </u>		+-+		
		·						
1	DD			psi 0054./				
chem-	1 4	Chimecas s	owner	VSI CO 1.7	<u>· </u>	+		1
		·				 		+
pariet	40	Days del 10	at MIDUI	saitefasto	2545	3		
parce		power re	ur your					
				. /		+		
9	QC3	Inspect &	owdu Co	et.				_
10	65		Toch.					
10	<u> </u>	Kanny E	,				, 1	
11	OC	Lene/21	/ Close .	W/O.		 		_
63	orda	Oroped III	Josh Well	/.				
	-1-7/	To vojus me	un-jun van					
						 		
].								<u> </u>
!			nnri IA	AINIADV ICO				
<u>'</u>		<u>L</u>	- PKFLII I	MINAU I IO	JUL	لـــــــــــــــــــــــــــــــــــــ		

Rev	Date	Change	Revised By	Approved
1101				